



Section 6: Installation Photographs



Improper installation of loading dock threshold.

- removable astragal bracket in the path of travel
- weather strip above threshold