



Section 6: Installation Photographs



**AVOID:** Horizontal precast joint to be  
Caulked with Ultra-low-modulus silicon sealant  
Dow 790 or Pecora 890, not grouted, at top of wall.

Joint to be  
caulked