



Section 6: Installation Photographs



AVOID: Finish of stair stringer/landing joint to be seamless and smooth. All exposed steel to meet AESS standards.

Poor joint finish