



Section 6: Installation Photographs



**Improper cleanout.
Cover should be located above base.**



**Improper cleanout.
Not flush with floor surface.**