



Section 6: Installation Photographs



Standard interior view window condition with applied glass stop on “secured” side of frame.

Glass stop on “secured side” of frame.